



CITY OF CAMBRIDGE
INTEROFFICE CORRESPONDENCE

To : James L. Sullivan
City Manager

Date : February 21, 1979

From : Conrad C. Fagone, Commissioner *cef*
Public Works Department

Reference

Subject : Council Order No. 8 - February 12, 1979 - Councillor Crane
Investigate Heating Problems at 105 Windsor Street

The department has investigated the heating problems at 105 Windsor Street on numerous occasions. The problem at 105 Windsor Street is that the heating system designed is inadequate for the building. This problem, coupled with the exposure of the bare walls, and renovations to insulate, have created drafts and total lack of heat.

Temporary electric heating units have been installed; however, permanent solutions to this problem cannot be made until final use of the building is determined, as it will involve a substantial sum of money which is not available at this time.

RECEIVED
FEB 21 4 11 PM '79
OFFICE OF THE
CITY MANAGER



CITY OF CAMBRIDGE

CAMBRIDGE, MASSACHUSETTS 02139
Tel. 498-9011


EXECUTIVE DEPARTMENT
JAMES L. SULLIVAN
City Manager

February 26, 1979

To the Honorable, the City Council:

With respect to Awaiting Report Item No. 22 relative to heating problems at 105 Windsor Street, enclosed please find copy of a report from Conrad C. Fagone, Commissioner of Public Works.

Very truly yours,



James L. Sullivan
City Manager

JLS/mbf
Enc.

5108

Response to Awaiting Report No. 22 re:
heating problems at 105 Windsor St.

In City Council,
February 26, 1979

2/26/79

Placed on File