



CITY OF CAMBRIDGE
Traffic, Parking and Transportation
57 Inman Street,
Cambridge, Massachusetts 02139

Susan E. Clippinger
Director

Administration	349-4700
Parking Violations	349-4705
Resident Parking	349-4701

February 5, 1997

TO: Robert Healy, City Manager

FROM: Susan E. Clippinger, Director 

RE: Council Order #076 dated June 3, 1996

SUBJECT: Safety issues at the corner of Norfolk Street and Bishop Allen Drive

The intersection of Norfolk and Bishop Allen Drive is a busy intersection bordered by a church and a public parking lot bordering Central Square. Sight lines at this intersection are limited. Each leg of the intersection carries approximately the same amount of traffic, the majority of which is through movements. In addition, this intersection experienced 10 reported accidents in the last two years. Saint Paul AME Life Center directly opposite parking lot 5 houses a day care and the Henry Buckner School

Therefore, we are installing an all way stop to increase the safety of the existing crossings and improve on the intersection safety for vehicles. The signs will be installed on or before February 18, 1997.



CITY OF CAMBRIDGE
CAMBRIDGE, MASSACHUSETTS 02139

TEL. 349-4300
FAX. 349-4307



EXECUTIVE DEPARTMENT
ROBERT W. HEALY
City Manager

RICHARD C. ROSSI
Deputy City Manager

February 10, 1997

To The Honorable, The City Council:

In response to Awaiting Report Item Number 4, regarding safety issues at the corner of Norfolk Street and Bishop Allen Drive, please find attached a report from Susan Clippinger, Director of Traffic, Parking and Transportation.

Very truly yours,

Robert W. Healy
City Manager

RWH/dls
attachment

Consent Agenda #5

5-69

Relative to Awaiting Report Item Number
Four, regarding safety issues at the
corner of Norfolk street and Bishop
Alen Drive.

In City Council February 10, 1997

PLACED ON FILE