



City of Cambridge

O-4.

IN CITY COUNCIL
June 25, 2001

COUNCILLOR REEVES
COUNCILLOR BORN
COUNCILLOR BRAUDE
COUNCILLOR DAVIS
MAYOR GALLUCCIO
VICE MAYOR MAHER
COUNCILLOR SULLIVAN
COUNCILLOR TOOMEY

WHEREAS: Howard Street is one of the city's older streets near the Charles River; and

WHEREAS: On Howard Street directly in front of the Abundant Life Church, there is an opening in the asphalt paving which is sizable and an opening which is hazardous and which people have stepped into, tripped and fallen; and

WHEREAS: Also on Howard Street, there is a portion of concrete sidewalk which has been raised by an abutting tree. The sidewalk is therefore uneven and can cause pedestrians to trip and fall; now therefore be it

ORDERED: That the City Manager be and hereby is requested to direct the Commissioner of Public Works to review these areas on Howard Street and to address them with dispatch.

In City Council June 25, 2001.

Adopted by the affirmative vote of nine members.

Attest:- D. Margaret Drury, City Clerk.

A true copy;

ATTEST:-

D. Margaret Drury
City Clerk

~~221 E. ...~~

Reverend

4/25

0.4

Whereas: Howard Street is one of the city's oldest streets near the Charles River and;

Whereas: On Howard Street directly in front of the Abundant Life Church, there is an opening in the asphalt paving which is sizeable and an opening which is hazardous and which people have stepped into, tripped and fallen.

Whereas Also on Howard Street there is a portion of concrete sidewalk which has been raised by an abutting tree.

The sidewalk is therefore uneven and can cause pedestrians to trip and fall.

Resolved: That the Department of Public Works be requested to review these areas on ~~the~~ Howard Street and to address them with dispatch.



City of Cambridge

O-4.

IN CITY COUNCIL

June 25, 2001

COUNCILLOR REEVES

WHEREAS: Howard Street is one of the city's older streets near the Charles River; and

WHEREAS: On Howard Street directly in front of the Abundant Life Church, there is an opening in the asphalt paving which is sizable and an opening which is hazardous and which people have stepped into, tripped and fallen; and

WHEREAS: Also on Howard Street, there is a portion of concrete sidewalk which has been raised by an abutting tree. The sidewalk is therefore uneven and can cause pedestrians to trip and fall; now therefore be it

ORDERED: That the City Manager be and hereby is requested to direct the Commissioner of Public Works to review these areas on Howard Street and to address them with dispatch.

189 Cm

Order #4

Defect of sidewalk and road in
front of Abundant Life Church on
Howard Street.

Councillor Reeves

In City Council June 25, 2001

ORDER ADOPTED