

IRWIN Engineers, Inc.

Chemical and Environmental

74 West Central Street
Natick, MA 01760

FAX (508) 653-8194

PHONE (508) 653-8007

September 17, 1998

Mayor's Office
City of Cambridge
795 Massachusetts Avenue
Cambridge, Massachusetts 02139

**RE: Public Involvement Activity Notification - 310 CMR 40.1400
RTN 3-17136
Genetics Institute, Inc.
87 Cambridge Park Drive
Cambridge, Massachusetts**


To whom it may concern:

On August 10, 1998, a release of 10 gallons of diesel fuel resulted from a ruptured fuel tank on a delivery truck. The release was onto pavement and did not enter soil or any drains before it was cleaned up with absorbent material. The Fire Department was on hand during the cleanup and other appropriate notifications were made at that time.

It is the opinion of J. Andrew Irwin, Licensed Site Professional (LSP), that a level of No Significant Risk and a Class A-1 Response Action Outcome (RAO) have been achieved, and that no further actions are required at this time.

Anyone interested in reviewing the RAO Statement and supporting information may send a written request to: DEP Northeast Regional Office, Bureau of Waste Site Cleanup, 205 Lowell Street, Wilmington, MA 01887 or call DEP's Service Center at (978)661-7600. Otherwise you may contact our offices to obtain a copy.

Very truly yours,
IRWIN Engineers, Inc.



J. Andrew Irwin, P.E., LSP
President

cc: Dames & Moore
Cambridge Fire Department
Cambridge Board of Health
Cambridge Conservation Commission
Department Environmental Protection Bureau of Waste Site Cleanup

Comm. & Rpts from City Officers 6395
#2

A communication was received from Mayor Duehay, transmitting a communication received from J. Andrew Irwin, P.E., LSP, President, transmitting a letter regarding a release of 10 gallons of diesel fuel resulted from a ruptured fuel tank on a delivery truck.

In City Council October 5, 1998

PLACED ON FILE