



CITY OF CAMBRIDGE
INTEROFFICE CORRESPONDENCE

To Mr. John H. Corcoran
City Manager

Date June 19, 1973

From Chief William J. Cremins
Fire Department

Reference

Subject

Council Order re: Replacement of Hydrant at 374 Cambridge Street

Sir:

This hydrant is on a 20" main with excellent volume and pressure. As you know, our system of water mains is not of the best and I would be most apprehensive, for the safety of the neighborhood, to lose this hydrant at this location.


On January 1, 1973 (this year) we had a General Alarm fire at Box 122. This hydrant was used by Engine Company #5, with excellent results.

I would recommend that it not be replaced.

Very truly yours,

William J. Cremins
Chief of Fire Department

7/19/73
67-1922-4
U1 MUL



CITY OF CAMBRIDGE

CAMBRIDGE, MASSACHUSETTS 02139
Tel. 876-6800

EXECUTIVE DEPARTMENT
JOHN H. CORCORAN
City Manager

June 25, 1973

To the Honorable, the City Council,

With reference to City Council order of June 4, 1973 I transmit herewith self-explanatory communication from William J. Cremins, Chief of the Fire Department relative to the replacement of hydrant at 374 Cambridge Street.

Very truly yours,

John H. Corcoran
City Manager

JHC/m

Self-explanatory communication from William J. Cremins, Chief of Fire Dept., relative to the replacement of hydrant at 374 Cambridge St.

COMMUNICATIONS SECTION
JULY 1, 1973

COMMUNICATIONS SECTION

OF THE CITY OF BOSTON
COMMUNICATIONS SECTION
JULY 1, 1973

COMMUNICATIONS SECTION

COMMUNICATIONS SECTION

In City Council,

June 25, 1973

6/25/73

Placed on File

COMMUNICATIONS SECTION

COMMUNICATIONS SECTION