




Ralph E. Dunphy
Commissioner

147 Hampshire Street
Cambridge, MA 02139
617-349-4800
TDD 617-349-4805

To: Robert W. Healy
City Manager

From:  Ralph E. Dunphy
Commissioner

Date: February 11, 1997

Subject: Council Order #085, dated 01/27/97
Re: Sewer Problem at Intersection of
Pearl Street and Massachusetts
Avenue

-REVISED-

The catch basin at Mass. Ave. and Pearl St. is scheduled to be replaced as part of the Central Sq. Project. The street has been lowered in the immediate vicinity of the catch basin and will not be completed until this summer. The re-location of the catch basin will be completed with the street work.

Immediate re-location of the catch basin was also considered. However, the catch basin location must also be coordinated with the re-location of several underground utilities, curb, sidewalk and light pole foundations thus preventing the re-location at the present time.

The catch basin has been temporarily sealed off and should not present any future odor problems.

97 FEB 13 AM 11:27
OFFICE OF THE CITY MANAGER





CITY OF CAMBRIDGE
CAMBRIDGE, MASSACHUSETTS 02139

TEL 349-4300
FAX 349-4307



EXECUTIVE DEPARTMENT
ROBERT W. HEALY
City Manager

RICHARD C. ROSSI
Deputy City Manager

February 24, 1997

To The Honorable, The City Council:

In response to Awaiting Report Item Number 29, regarding sewer odors at the Intersection of Pearl Street and Massachusetts Avenue, please find attached a report submitted by Ralph Dunphy, Commissioner of Public Works.

Very truly yours,

Robert W. Healy
City Manager

RWH/dls

Consent Agenda #6.

S-88

Relative to Awaiting Report Item
Number Twenty-Five, regarding sewer
odors at the intersection of Pearl
Street and Massachusetts Avenue.

In City Council February 24, 1997.

PLACED ON FILE